
Chisels—Safety





BLUNT TOOLS CAUSE:




Horizontal Paring:





N.B. Keep all parts of the body behind cutting edge.


Note position of elbow and position of hands!














Published by the Education Department 1983 set 3